

Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237 Telephone: 800.347.4010 Lead in Drinking Water Analysis Report

Report Number: 21-06-03708

Received Date: 06/23/2021
Reported Date: 07/22/2021
Sampled By: Christine Schultz

Tech Certification #:

Client: Stohl Environmental

3860 California Road Orchard Park, NY 14127

Project/Test Address: 2020L-121.7; Lincoln Elementary School; 301 Front St; Jamestown, NY 14701

Client Number:

33-5980

Laboratory Results

Fax Number: 716-312-8092

| Lab Sample Number | Client Sample ID | Collection Date | Collection Location | Concentration ug/L (ppb) | Analysis Date | Narrative ID |
|----------------------|---------------------|--------------------|---|--------------------------|------------------|-----------------|
| 21-06-03708-001 | 121.7-1 | 06/09/2021 | SERVICE CONNECTION PE OFFICE 1S-1 | 24.7 | 07/21/2021 | |
| 21-06-03708-002 | 121.7-2 | 06/09/2021 | CORRIDOR BY GYM FOUNTAIN 1C-1 | 1.34 | 07/21/2021 | |
| 21-06-03708-003 | 121.7-3 | 06/09/2021 | BASEMENT ART ROOM 1F-1 | 2.06 | 07/21/2021 | |
| 21-06-03708-004 | 121.7-4 | 06/09/2021 | SPEECH ROOM 104 LAV 1F- 42 | 4.54 | 07/21/2021 | |
| 21-06-03708-005 | 121.7-5 | 06/09/2021 | 1ST FLOOR ART ROOM LAV 1F-43 | 3.86 | 07/21/2021 | |
| 21-06-03708-006 | 121.7-6 | 06/09/2021 | CLASSROOM 205 SINK 1F- 31 | <1.00 | 07/21/2021 | |
| 21-06-03708-007 | 121.7-7 | 06/09/2021 | CLASSROOM 205 BUBBLER 1A-2 | <1.00 | 07/21/2021 | |
| 21-06-03708-008 | 121.7-8 | 06/09/2021 | CLASSROOM 207 SINK 1F- 32 | 13.8 | 07/21/2021 | |
| 21-06-03708-009 | 121.7-9 | 06/09/2021 | KITCHEN 3 BAY RIGHT 1F-4 | 2.30 | 07/21/2021 | |
| 21-06-03708-010 | 121.7-10 | 06/09/2021 | CLASSROOM 213 SINK 1F- 33 | 2.78 | 07/21/2021 | |
| 21-06-03708-011 | 121.7-11 | 06/09/2021 | CLASSROOM 213 BUBBLER 1A-1 | 10.3 | 07/21/2021 | |
| 21-06-03708-012 | 121.7-12A | 06/09/2021 | CORRIDOR FOUNTAIN BY NURSE PUSH BAR 1C-2 | <1.00 | 07/21/2021 | |
| 21-06-03708-013 | 121.7-12B | 06/09/2021 | CORRIDOR FOUNTAIN BY NURSE 1C-2 | <1.00 | 07/21/2021 | |

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-06-03708

Project/Test Address: 2020L-121.7; Lincoln Elementary School; 301 Front St; Jamestown, NY 14701

| Lab Sample Number | Client Sample ID | Collection Date | Collection Location | Concentration ug/L (ppb) | Analysis Date | Narrative ID |
|----------------------|---------------------|--------------------|-------------------------------------|--------------------------|------------------|-----------------|
| 21-06-03708-014 | 121.7-13 | 06/09/2021 | NURSE LEFT 1F-2 | 1.07 | 07/21/2021 | |
| 21-06-03708-015 | 121.7-14 | 06/09/2021 | NURSE RIGHT 1F-3 | <1.00 | 07/21/2021 | |
| 21-06-03708-016 | 121.7-15 | 06/09/2021 | CLASSROOM 251 SINK 1F-5 | 4.00 | 07/21/2021 | |
| 21-06-03708-017 | 121.7-16 | 06/09/2021 | CLASSROOM 251 STORAGE SINK 1F-34 | 19.1 | 07/21/2021 | |
| 21-06-03708-018 | 121.7-17 | 06/09/2021 | CLASSROOM 255 SINK 1F- 35 | 2.84 | 07/21/2021 | |
| 21-06-03708-019 | 121.7-18 | 06/09/2021 | CORRIDOR BY 236 FOUNTAIN 1C-3 | <1.00 | 07/21/2021 | |
| 21-06-03708-020 | 121.7-19 | 06/09/2021 | CLASSROM 261 SINK 1F-36 | <1.00 | 07/21/2021 | |
| 21-06-03708-021 | 121.7-20 | 06/09/2021 | CLASSROOM 261 BUBBLER 1A-4 | 3.69 | 07/21/2021 | |
| 21-06-03708-022 | 121.7-21 | 06/09/2021 | CLASSROOM 269 SINK 1F- 38 | 1.56 | 07/21/2021 | |
| 21-06-03708-023 | 121.7-22 | 06/09/2021 | CLASSROOM 269 BUBBLER 1A-5 | 3.52 | 07/21/2021 | |
| 21-06-03708-024 | 121.7-23 | 06/09/2021 | OFFICE 302/301 SINK 1F-6 | <1.00 | 07/21/2021 | |
| 21-06-03708-025 | 121.7-24 | 06/09/2021 | CLASSROOM 405 SINK 1F- 15 | 1.07 | 07/21/2021 | |
| 21-06-03708-026 | 121.7-25 | 06/09/2021 | CLASSROOM 405 BUBBLER 1A-19 | <1.00 | 07/21/2021 | |
| 21-06-03708-027 | 121.7-26 | 06/09/2021 | FOUNTAIN OUTSIDE 405 1C-6 | <1.00 | 07/21/2021 | |
| 21-06-03708-028 | 121.7-27 | 06/09/2021 | CLASSROOM 407 SINK 1F- 16 | 1.26 | 07/21/2021 | |
| 21-06-03708-029 | 121.7-28 | 06/09/2021 | CLASSROOM 407 BUBBLER 1A-18 | <1.00 | 07/21/2021 | |
| 21-06-03708-030 | 121.7-29 | 06/09/2021 | CONF ROOM 412 SINK 1F-8 | 2.38 | 07/21/2021 | |
| 21-06-03708-031 | 121.7-30 | 06/09/2021 | ROOM 413 SINK 1F-18 | 4.68 | 07/21/2021 | |
| 21-06-03708-032 | 121.7-31 | 06/09/2021 | ROOM 413 BUBBLER 1A-17 | 1.40 | 07/21/2021 | |
| 21-06-03708-033 | 121.7-32 | 06/09/2021 | FOUNTAIN OUTSIDE 415 1C-5 | 5.93 | 07/21/2021 | |

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-06-03708

Project/Test Address: 2020L-121.7; Lincoln Elementary School; 301 Front St; Jamestown, NY 14701

| Lab Sample Number | Client Sample ID | Collection Date | Collection Location | Concentration ug/L (ppb) | Analysis Date | Narrative ID |
|----------------------|---------------------|--------------------|---------------------------------------|--------------------------|------------------|-----------------|
| 21-06-03708-034 | 121.7-33 | 06/09/2021 | ROOM 415 SINK 1F-19 | 1.79 | 07/21/2021 | |
| 21-06-03708-035 | 121.7-34 | 06/09/2021 | ROOM 415 BUBBLER 1A-16 | 1.60 | 07/21/2021 | |
| 21-06-03708-036 | 121.7-35 | 06/09/2021 | ROOM 421 SINK 1F-20 | 1.76 | 07/21/2021 | |
| 21-06-03708-037 | 121.7-36 | 06/09/2021 | ROOM 421 BUBBLER 1A-15 | 2.76 | 07/21/2021 | |
| 21-06-03708-038 | 121.7-37 | 06/09/2021 | ROOM 435 SINK 1F-21 | 1.23 | 07/21/2021 | |
| 21-06-03708-039 | 121.7-38 | 06/09/2021 | ROOM 435 BUBBLER 1A-14 | 4.47 | 07/21/2021 | |
| 21-06-03708-040 | 121.7-39 | 06/09/2021 | FACULTY ROOM 437 SINK 1F-7 / 1F-22 | 1.11 | 07/21/2021 | |
| 21-06-03708-041 | 121.7-40 | 06/09/2021 | FACULTY ROOM 437 BUBBLER A1-13 | <1.00 | 07/21/2021 | |
| 21-06-03708-042 | 121.7-41 | 06/09/2021 | ROOM 449 SINK 1F-24 | 8.35 | 07/21/2021 | |
| 21-06-03708-043 | 121.7-42 | 06/09/2021 | ROOM 449 BUBBLER 1A-12 | 2.14 | 07/21/2021 | |
| 21-06-03708-044 | 121.7-43 | 06/09/2021 | ROOM 451 SINK 1F-25 | 1.25 | 07/21/2021 | |
| 21-06-03708-045 | 121.7-44 | 06/09/2021 | ROOM 451 BUBBLER 1A-11 | <1.00 | 07/21/2021 | |
| 21-06-03708-046 | 121.7-45 | 06/09/2021 | ROOM 445 SINK 1F-26 | 1.30 | 07/21/2021 | |
| 21-06-03708-047 | 121.7-46 | 06/09/2021 | ROOM 455 BUBBLER 1A-10 | <1.00 | 07/21/2021 | |
| 21-06-03708-048 | 121.7-47 | 06/09/2021 | FOUNTAIN OUTSIDE ROOM 461 1C-4 | <1.00 | 07/21/2021 | |
| 21-06-03708-049 | 121.7-48 | 06/09/2021 | ROOM 461 RIGHT SINK 1F- 27 | 1.81 | 07/21/2021 | |
| 21-06-03708-050 | 121.7-49 | 06/09/2021 | ROOM 461 RIGHT BUBBLER 1A-9 | 1.86 | 07/21/2021 | |
| 21-06-03708-051 | 121.7-50 | 06/09/2021 | ROOM 461 LEFT SINK 1F-28 | 1.64 | 07/21/2021 | |
| 21-06-03708-052 | 121.7-51 | 06/09/2021 | ROOM 461 LEFT BUBBLER 1A-8 | 1.14 | 07/22/2021 | |
| 21-06-03708-053 | 121.7-52 | 06/09/2021 | ROOM 469 SINK 1F-29 | 2.02 | 07/22/2021 | |

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-06-03708

Project/Test Address: 2020L-121.7; Lincoln Elementary School; 301 Front St;

Jamestown, NY 14701

| | ab Sample Number | Client Sample ID | Collection Date | Collection Location | Concentration ug/L (ppb) | Analysis Date | Narrative ID |
|------|---------------------|---------------------|--------------------|------------------------------|--------------------------|------------------|-----------------|
| 21-0 | 06-03708-054 | 121.7-53 | 06/09/2021 | ROOM 469 BUBBLER 1A-7 | 135 | 07/22/2021 | |
| 21-0 | 06-03708-055 | 121.7-54 | 06/09/2021 | ROOM 450 SINK 1F-30 | 2.02 | 07/22/2021 | |
| 21-0 | 06-03708-056 | 121.7-55 | 06/09/2021 | ROOM 450 BUBBLER 1A-6 | 1.38 | 07/22/2021 | |
| 21-0 | 06-03708-057 | 121.7-56 | 06/09/2021 | LIBRARY WORK ROOM 1F-9 | 40.0 | 07/22/2021 | |
| 21-0 | 06-03708-058 | 121.7-57 | 06/09/2021 | ROOM 503 SINK 1F-11 | 1.88 | 07/22/2021 | |
| 21-0 | 06-03708-059 | 121.7-58 | 06/09/2021 | ROOM 503 BUBBLER 1A-20 | 3.47 | 07/22/2021 | |
| 21-0 | 06-03708-060 | 121.7-59 | 06/09/2021 | ROOM 503 WORK AREA 1F- 10 | 5.59 | 07/22/2021 | |

Method: EPA 200.8
Analyst: Ailea Cabatbat
Accreditation #: NY 11714

Reviewed By Authorized Signatory:

Melisoa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND

ug/L= micrograms per liter

ppb = parts per billion





Submitted to: (Lab Name)

EHS

STOHL Job #

2020L-121.7

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM

Jamestown CSD

Contact: Carl Pillittieri

Building: Lincoln Elementary School

Location: 301 Front St. Jamestown, NY 14701

LEAD

Notes:

Client:

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround

Outlet Type

DF

S

S

S

S

В

S

S

S

Time 5:20

5:22

5:24

5:26

5:28

5:30

5:32

5:34

5:36

5:38

20 Days

| Sample # | Location | |
|-----------|--|---|
| 121.7-1 | Service Connection PE Office [1S-1] | |
| 121.7-2 | Corridor by Gym Fountain [1C-1] | |
| 121.7-3 | Basement Art Room [1F-1] | |
| 121.7-4 | Speech Room 104 Lav [1F-42] | *************************************** |
| 121.7-5 | 1st Floor Art Room Lav [1F-43] | |
| 121.7-6 | Classroom 205 Sink [1F-31] | |
| 121.7-7 | Classroom 205 Bubbler [1A-2] | |
| 121.7-8 | Classroom 207 Sink [1F-32] | |
| 121.7-9 | Kitchen 3 Bay Right [1F-4] | |
| 121.7-10 | Classroom 213 Sink [1F-33] | |
| 121.7-11 | Classroom 213 Bubbler [1A-1] | |
| 121.7-12A | Corridor Fountain by Nurse - Push Bar [1C-2] | |
| 121.7-12B | Corridor Fountain by Nurse [1C-2] | |
| 121.7-13 | Nurse Left [1F-2] | |
| 121.7-14 | Nurse Right [1F-3] | |
| 121.7-15 | Classroom 251 Sink [1F-5] | |
| 121.7-16 | Classroom 251 Storage Sink [1F-34] | |
| 121.7-17 | Classroom 255 Sink [1F-35] | |

21-06-03708



Due Date: 07/22/2021 (Thursday) AE

| В | 5:40 |
|-----|------|
| DF | 5:42 |
| DFB | 5:44 |
| S | 5:46 |
| S | 5:48 |
| S | 5:50 |
| S | 5:52 |
| S | 5:54 |
| | |
| | |

| Please e-mail lab results to labs@stohlenv.com | necked, also e-mail results to: | Ehenderson@StohlEnv.com |
|---|---------------------------------|-------------------------|
| Sampled By: Christine Schultz Print Name | Stohl Env: Christine Schultz | Date: 6/9/2021 |
| Relinquished By: 2 + 10 Print Name | Stohl Env: Eric Henderson Jr. | Date: 6/19/2021 |
| Received (Name / Lab): | Date: 74473 | Time: 500 LWB |
| Sample Login (Name / Lab): Tran Bloom than Rus- | Date: 7/4/21 | Time: 5/00PM |
| Analysis (Name / Lab): | Date: 11111 | Time: 1190m |
| QA/QC Review (Name / Lab): | Date: | Time: |
| Archived / Released:QA/QC InterLAB Use: | Date: | Time: |

Page

_1 of _4



Submitted to: (Lab Name)

EHS

STOHL Job #

20201 -121 7

| | 3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM | | 20201-121.7 | |
|-------------|---|---------|--------------------------------------|--|
| Client: | Jamestown CSD | Contac | ct: Carl Pillittieri | |
| Building: | Lincoln Elementary School | Locatio | n: 301 Front St. Jamestown, NY 14701 | |
| <u>LEAD</u> | | | Turnaround | |
| Water by | SM 19, 21 - 23 3113B (-04, -10) | X | 20 Days | |
| | | | | |

| Sample # | Location | Outlet Type | Time |
|----------|---------------------------------|-------------|------|
| 121.7-18 | Corridor by 236 Fountain [1C-3] | DF | 5:56 |
| 121.7-19 | Classroom 261 Sink [1F-36] | S | 5:58 |
| 121.7-20 | Classroom 261 Bubbler [1A-4] | В | 6:00 |
| 121.7-21 | Classroom 269 Sink [1F-38] | S | 6:02 |
| 121.7-22 | Classroom 269 Bubbler [1A-5] | В | 6:04 |
| 121.7-23 | Office 302/301 Sink [1F-6] | S | 6:06 |
| 121.7-24 | Classroom 405 Sink [1F-15] | S | 6:08 |
| 121.7-25 | Classroom 405 Bubbler [1A-19] | В | 6:10 |
| 121.7-26 | Fountain Outside 405 [1C-6] | DF | 6:12 |
| 121.7-27 | Classroom 407 Sink [1F-16] | S | 6:14 |
| 121.7-28 | Classroom 407 Bubbler [1A-18] | В | 6:16 |
| 121.7-29 | Conf Room 412 Sink [1F-8] | S | 6:18 |
| 121.7-30 | Room 413 Sink [1F-18] | S | 6:20 |
| 121.7-31 | Room 413 Bubbler [1A-17] | В | 6:22 |
| 121.7-32 | Fountain Outside 415 [1C-5] | DF | 6:24 |
| 121.7-33 | Room 415 Sink [1F-19] | S | 6:26 |
| 121.7-34 | Room 415 Bubbler [1A-16] | В | 6:28 |
| 121.7-35 | Room 421 Sink [1F-20] | S | 6:30 |

| Notes: Please e-mail lab results to lat | os@stohlenv.com | | Ehenderson@StohlEnv.com |
|--|-------------------------|-------------------------------|-------------------------|
| Sampled By: Christine So | chultz Print Name | Stohl Env: Christine Schultz | Date: 6/9/2021 |
| Relinquished By: _ £ + +4 | Print Name | Stohl Env: Eric Henderson Jr. | Date: 6/19/2021 |
| Received (Name / Lab): | KTHARRIS KULCUL | Date: 6/23/21 | Time: 12:00 pm |
| Sample Login (Name / Lab): | Tragi Bloom & fran Alan | Date: 7/6/21 | Time: 504PM |
| Analysis (Name / Lab): | A.C. Alpalabuthart | Date: | Time: |
| QA/QC Review (Name / Lab): | heim | Date: | Time: |
| Archived / Released: | _QA/QC InterLAB Use: | _Date: | Time: |

Page <u>2</u> of <u>4</u>



Submitted to: (Lab Name)

EHS

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM STOHL Job#

2020L-121.7

| | WWW.OTOTICETWINOIWIERTAE.OOM | | | |
|-----------|---------------------------------|-------------|-----------------------------------|--|
| Client: | Jamestown CSD | Contact: C | Carl Pillittieri | |
| Building: | Lincoln Elementary School | Location: 3 | 301 Front St. Jamestown, NY 14701 | |
| LEAD | | | Turnaround | |
| Water by | SM 19, 21 - 23 3113B (-04, -10) | X | 20 Days | |
| | | | | |

| Sample # | Location | Outlet Type | Time |
|----------|--------------------------------------|-------------|------|
| 121.7-36 | Room 421 Bubbler [1A-15] | В | 6:32 |
| 121.7-37 | Room 435 Sink [1F-21] | S | 6:34 |
| 121.7-38 | Room 435 Bubbler [1A-14] | В | 6:36 |
| 121.7-39 | Faculty Room 437 Sink [1F-7 / 1F-22] | S | 6:38 |
| 121.7-40 | Faculty Room 437 Bubbler [1A-13] | В | 6:40 |
| 121.7-41 | Room 449 Sink [1F-24] | S | 6:42 |
| 121.7-42 | Room 449 Bubbler [1A-12] | В | 6:44 |
| 121.7-43 | Room 451 Sink [1F-25] | S | 6:46 |
| 121.7-44 | Room 451 Bubbler [1A-11] | В | 6:48 |
| 121.7-45 | Room 455 Sink [1F-26] | S | 6:50 |
| 121.7-46 | Room 455 Bubbler [1A-10] | В | 6:52 |
| 121.7-47 | Fountain Outside Room 461 [1C-4] | DF | 6:54 |
| 121.7-48 | Room 461 Right Sink [1F-27] | S | 6:56 |
| 121.7-49 | Room 461 Right Bubbler [1A-9] | В | 6:58 |
| 121.7-50 | Room 461 Left Sink [1F-28] | S | 7:00 |
| 121.7-51 | Room 461 Left Bubbler [1A-8] | В | 7:02 |
| 121.7-52 | Room 469 Sink [1F-29] | S | 7:04 |
| 121.7-53 | Room 469 Bubbler [1A-7] | В | 7:06 |

| Notes: Please e-mail lab results to labs@stohlenv.com | 1 | | Ehenderson@StohlEnv.com |
|--|-----------------|-------------------------------|-------------------------|
| Sampled By: Christine Schultz | Print Name | Stohl Env: Christine Schultz | Date: 6/9/2021 |
| Relinquished By: 5. +4-l0 | Print Name | Stohl Env: Eric Henderson Jr. | Date: 6/19/2021 |
| Received (Name / Lab): | K Dlane | Date: 6/23/21 | Time: 12:00 pm |
| Sample Login (Name / Lab): Trang Black) 4 | hou Blan | Date: 3/6/21 | Time: 50841/ |
| Analysis (Name / Lab): | filea (abetbect | Date: 1WV | Time: $17.9pm$ |
| QA/QC Review (Name / Lab): | Let - | Date: | Time: |
| Archived / Released:QA/QC InterLA | B Use: | _Date: | Time: |

Page

<u>3</u> of <u>4</u>



S

STOHL Job#

2020L-121.7

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM

| Submitted to: (Lab Name) | EHS |
|--------------------------|-----|
| , | |

| Client: | Jamestown CSD | Contact: Carl Pil | llittieri | Material and a second s |
|-----------|---------------------------------|-------------------|---|--|
| Building: | Lincoln Elementary School | Location: 301 Fro | Location: 301 Front St. Jamestown, NY 14701 | |
| LEAD | | | Turnaround | |
| Water by | SM 19, 21 - 23 3113B (-04, -10) | XX | 20 Days | |
| 8 | | | | |

| Sample # | Location | Outlet Type | Time |
|----------|---|-------------|----------|
| 121.7-54 | Room 450 Sink [1F-30] | S | 7:08 |
| 121.7-55 | Room 450 Bubbler [1A-6] | В | 7:10 |
| 121.7-56 | Library Work Room [1F-9] | S | 7:12 |
| 121.7-57 | Room 503 Sink [1F-11] | S | 7:14 |
| 121.7-58 | Room 503 Bubbler [1A-20] | В | 7:16 |
| 121.7-59 | Room 503 Work Area Sink [1F-10] | S | 7:18 |
| | | | |
| | | | |
| | | | <u> </u> |
| | | | <u> </u> |
| | | | |
| | | | |
| | | | <u> </u> |
| | | | |
| | | | |
| | The Administration of | | |
| · | | | |
| | , | | |
| | | | |

| Notes: Please e-mail lab results to lab | s@stohlenv.com | | Ehenderson@StohlEnv.com |
|--|----------------------|-------------------------------|-------------------------|
| Sampled By: Christine Sc | hultz Print Name | Stohl Env: Christine Schultz | Date: 6/9/2021 |
| Relinquished By: | Print Name | Stohl Env: Eric Henderson Jr. | Date: 6/19/2021 |
| Received (Name / Lab): | KTHARRIS ON OLA | water 6232) | Time: 1200 pm |
| Sample Login (Name / Lab): 7 | raci Bloom / Lay Blo | Date: 7/6/21 | Time: 509PM |
| Analysis (Name / Lab): | Alley Capathot | Date: 1 | Time: 219m |
| QA/QC Review (Name / Lab): | prim | Date: | Time: 10h |
| Archived / Released: | QA/QC InterLAB Use: | _ Date: | Time: |
| | | | |

Page

_4 of _4_