



Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237  
Telephone: 800.347.4010

## Lead in Drinking Water Analysis Report

**Client:** Stohl Environmental  
3860 California Road  
Orchard Park, NY 14127

**Report Number:** 21-06-03718

**Received Date:** 06/23/2021  
**Reported Date:** 07/22/2021  
**Sampled By:** Christine Schultz  
**Tech Certification #:**

**Project/Test Address:** 2020L-121.2; Jefferson Middle School; 195 Martin Rd; Jamestown NY, 14701

**Client Number:**  
33-5980

**Fax Number:**  
716-312-8092

# Laboratory Results

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03718-001	121.2-1	06/08/2021	BOILER ROOM SERVICE CONNECTION 1S-1	8.43	07/20/2021	
21-06-03718-002	121.2-2	06/08/2021	KITCHEN SERVING LINE HAND WASH 1F-3	2.95	07/20/2021	
21-06-03718-003	121.2-3	06/08/2021	KITCHEN HAND WASH 1F-2	9.44	07/20/2021	
21-06-03718-004	121.2-4	06/08/2021	KITCHEN 3 BAY RIGHT 1F-5	20.2	07/20/2021	
21-06-03718-005	121.2-5	06/08/2021	KITCHEN EAST WALL 1F-5	35.4	07/20/2021	
21-06-03718-006	121.2-6	06/08/2021	CUSTODIAL AREA SINK 1F-1	4.51	07/20/2021	
21-06-03718-007	121.2-7	06/08/2021	EMPLOYEE BREAK ROOM 1F-6	1.42	07/20/2021	
21-06-03718-008	121.2-8	06/08/2021	CONFERENCE ROOM LEFT 1F-7	4.77	07/20/2021	
21-06-03718-009	121.2-9	06/08/2021	CONFERENCE ROOM RIGHT 1F-8	9.04	07/20/2021	
21-06-03718-010	121.2-10	06/08/2021	SUPERINTENDENTS OFFICE 1F-9	<1.00	07/20/2021	
21-06-03718-011	121.2-11	06/08/2021	CORRIDOR OUTSIDE DISTRICT OFFICES 1C-1	2.54	07/20/2021	
21-06-03718-012	121.2-12	06/08/2021	BOE TEACHERS CENTER KITCHENETTE 1F-4	3.44	07/20/2021	
21-06-03718-013	121.2-13	06/08/2021	FOUNTAIN OUTSIDE B SECTION BOYS LAV 1C-7	11.9	07/20/2021	

# Environmental Hazards Services, L.L.C

**Client Number:** 33-5980

**Report Number:** 21-06-03718

**Project/Test Address:** 2020L-121.2; Jefferson Middle School; 195 Martin Rd;  
Jamestown NY, 14701

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03718-014	121.2-14	06/08/2021	FOUNTAIN OUTSIDE B SECTION GIRLS LAV 1C-8	2.48	07/20/2021	
21-06-03718-015	121.2-15	06/08/2021	TEACHER LOUNGE B SECTION 1F-12	4.74	07/20/2021	
21-06-03718-016	121.2-16	06/08/2021	FOUNTAIN BETWEEN B SECTION SINGLE LAVS 1C-9	<1.00	07/20/2021	
21-06-03718-017	121.2-17	06/08/2021	MUSIC ROOM 1F-19	<1.00	07/20/2021	
21-06-03718-018	121.2-18	06/08/2021	ORCHESTRA ROOM 1F-20	7.78	07/20/2021	
21-06-03718-019	121.2-19	06/08/2021	CHORUS ROOM B20 1F-11	4.53	07/20/2021	
21-06-03718-020	121.2-20	06/08/2021	LEFT FOUNTAIN BETWEEN AUDITORIUM LAVS 1C-10	<1.00	07/20/2021	
21-06-03718-021	121.2-21	06/08/2021	RIGHT FOUNTAIN BETWEEN AUDITORIUM LAVS	<1.00	07/20/2021	
21-06-03718-022	121.2-22	06/08/2021	VISITING TEAM LOCKER ROOM 1A-1	2.61	07/20/2021	
21-06-03718-023	121.2-23	06/08/2021	CORRIDOR OUTSIDE LOCKER ROOMS 1C-23	11.9	07/20/2021	
21-06-03718-024	121.2-24A	06/08/2021	GYM LOBBY FOUNTAIN 1C-13	<1.00	07/20/2021	
21-06-03718-025	121.2-24B	06/08/2021	GYM LOBBY FOUNTAIN 1C-13	<1.00	07/20/2021	
21-06-03718-026	121.2-25	06/08/2021	FOUNTAIN OUTSIDE A SECTION BOYS LAV 1C-2	48.4	07/20/2021	
21-06-03718-027	121.2-26	06/08/2021	FOUNTAIN OUTSIDE OF A SECTION GIRLS LAV 1C-3	29.4	07/20/2021	
21-06-03718-028	121.2-27	06/08/2021	FOUNTAIN BETWEEN A SECTION SINGLE LAVS 1C-4	<1.00	07/20/2021	
21-06-03718-029	121.2-28	06/08/2021	NURSE OFFICE 1F-14	1.84	07/20/2021	
21-06-03718-030	121.2-29	06/08/2021	HOME EC ROOM A9 FRONT LEFT 1F-12	3.69	07/20/2021	
21-06-03718-031	121.2-30	06/08/2021	HOME EC ROOM A9 FRONT RIGHT 1F-13	4.31	07/20/2021	
21-06-03718-032	121.2-31	06/08/2021	HOME EC ROOM A9 REAR LEFT 1F-11	3.75	07/20/2021	
21-06-03718-033	121.2-32	06/08/2021	HOME EC ROOM A9 REAR RIGHT 1F-10	3.38	07/20/2021	

# Environmental Hazards Services, L.L.C

**Client Number:** 33-5980

**Report Number:** 21-06-03718

**Project/Test Address:** 2020L-121.2; Jefferson Middle School; 195 Martin Rd;  
Jamestown NY, 14701

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03718-034	121.2-33	06/08/2021	A2 WING FOUNTAIN LEFT 1C-5	<1.00	07/20/2021	
21-06-03718-035	121.2-34	06/08/2021	A2 WING FOUNTAIN RIGHT 1C-6	<1.00	07/20/2021	
21-06-03718-036	121.2-35	06/08/2021	CONCESSION STAND LEFT 1F-16	2.90	07/20/2021	
21-06-03718-037	121.2-36	06/08/2021	CONCESSION STAND CENTER 1F-17	3.08	07/20/2021	
21-06-03718-038	121.2-37	06/08/2021	CONCESSION STAND RIGHT PORCELAIN 1F-18	31.4	07/20/2021	

**Method:** EPA 200.8

**Analyst:** Ailea Cabatbat

**Accreditation #:** NY 11714

Reviewed By Authorized Signatory:

*Melissa Kanode*

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND                      ug/L= micrograms per liter                      ppb = parts per billion



3860 California Road, Orchard Park, New York 14127  
PHONE (716) 312-0070 FAX (716) 312-8092  
WWW.STOHLENVIRONMENTAL.COM

## Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-121.2

Client: Jamestown CSD

Contact: Carl Pillitteri

Building: Jefferson Middle School

Location: 195 Martin Rd Jamestown, NY 14701

### LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
121.2-1	Boiler Room Service Connection [1S-1]	S	2:00
121.2-2	Kitchen Serving Line Hand Wash [1F-3]	S	2:02
121.2-3	Kitchen Hand Wash [1F-2]	S	2:04
121.2-4	Kitchen 3 Bay Right [1F-5]	S	2:06
121.2-5	Kitchen East Wall [1F-5]	S	2:08
121.2-6	Custodial Area Sink [1F-1]	S	2:10
121.2-7	Employee Break Room [1F-6]	S	2:12
121.2-8	Conference Room Left [1F-7]	S	2:14
121.2-9	Conference Room Right [1F-8]	S	2:16
121.2-10	Superintendents Office [1F-9]	S	2:18
121.2-11	Corridor Outside District Offices [1C-1]	DF	2:20
121.2-12	BOE Teachers Center Kitchenette [1F-4]	S	2:22
121.2-13	Fountain Outside B Section Boys Lav [1C-7]	DF	2:24
121.2-14	Fountain Outside B Section Girls Lav [1C-8]	DF	2:26
121.2-15	Teachers Lounge B Section [1F-12]	S	2:28
121.2-16	Fountain Between B Section Single Lavs [1C-9]	DF	2:30
121.2-17	Music Room [1F-19]	S	2:32
121.2-18	Orchestra Room [1F-20]	S	2:34

21-06-03718



Due Date:  
07/22/2021  
(Thursday)  
AE

### Notes:

Please e-mail lab results to [labs@stohlenv.com](mailto:labs@stohlenv.com)

☒ If checked, also e-mail results to:

[Ehenderson@StohlEnv.com](mailto:Ehenderson@StohlEnv.com)

Sampled By: Christine Schultz Print Name Christine Schultz Date: 6/8/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Date: 6/19/2021

Received (Name / Lab): KTHARRIS K HARRIS Date: 6/23/21 Time: 12:12 PM

Sample Login (Name / Lab): Trace Bloom / Sharon Bloom Date: 7/7/21 Time: 7:43 AM

Analysis (Name / Lab): Alfred Alabaster Date: 7/10/21 Time: 3pm

QA/QC Review (Name / Lab): Melvin Date: 7/21/21 Time: Run

Archived / Released: \_\_\_\_\_ QA/QC InterLAB Use: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_



# Chain of Custody Document

3860 California Road, Orchard Park, New York 14127  
PHONE (716) 312-0070 FAX (716) 312-8092  
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-121.2

Client: Jamestown CSD

Contact: Carl Pillitteri

Building: Jefferson Middle School

Location: 195 Martin Rd Jamestown, NY 14701

## LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
121.2-19	Chorus Room B20 [1F-11]	S	2:36
121.2-20	Left Fountain Between Auditorium Lavs [1C-10]	DF	2:38
121.2-21	Right Fountain Between Auditorium Lavs	DF	2:40
121.2-22	Visiting Team Locker Room [1A-1]	B	2:42
121.2-23	Corridor Outside Locker Rooms [1C-23]	DF	2:44
121.2-24A	Gym Lobby Fountain [1C-13]	DF	2:46
121.2-24B	Gym Lobby Fountain [1C-13]	DFB	2:48
121.2-25	Fountain Outside A Section Boys Lav [1C-2]	DF	2:50
121.2-26	Fountain Outside of A Section Girls Lav [1C-3]	DF	2:52
121.2-27	Fountain Between A Section Single Lavs [1C-4]	DF	2:54
121.2-28	Nurse Office [1F-14]	S	2:56
121.2-29	Home Ec Room A9 Front Left [1F-12]	S	2:58
121.2-30	Home Ec Room A9 Front Right [1F-13]	S	3:00
121.2-31	Home Ec Room A9 Rear Left [1F-11]	S	3:02
121.2-32	Home Ec Room A9 Rear Right [1F-10]	S	3:04
121.2-33	A2 Wing Fountain Left [1C-5]	DF	3:06
121.2-34	A2 Wing Fountain Right [1C-6]	DF	3:08
121.2-35	Concession Stand Left [1F-16]	S	3:10

## Notes:

Please e-mail lab results to [labs@stohlenv.com](mailto:labs@stohlenv.com)

[Ehenderson@StohlEnv.com](mailto:Ehenderson@StohlEnv.com)

Sampled By: Christine Schultz Print Name Christine Schultz Date: 6/8/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Date: 6/19/2021

Received (Name / Lab): KTHARRIS Kula Date: 6/23/21 Time: 12:12 PM

Sample Login (Name / Lab): Travis Bloom Date: 7/7/21 Time: 7:47 AM

Analysis (Name / Lab): Alexa Caballero Date: 7/20/21 Time: 3 pm

QA/QC Review (Name / Lab): M. Smith Date: 7/21/21 Time: noon

Archived / Released: QA/QC InterLAB Use: Date:  Time:



STOHL Job # 2020L-121.2

Location: 195 Martin Rd Jamestown, NY 14701

x

20 Days

Ehenderson@StohlEnv.com

Archived / Released:                      QA/QC InterLAB Use:                      Date:                      Time: