



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Report Number: 21-06-03801

Received Date: 06/23/2021
Reported Date: 07/19/2021
Sampled By: Christine Schultz
Tech Certification #:

Project/Test Address: 2020L-121.4; Washington Middle School; 159 Buffalo St; Jamestown, NY 14701

Client Number:
33-5980

Laboratory Results

Fax Number:
716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03801-001	121.4-1	06/07/2021	NURSE MAIN 1F-1	6.32	07/19/2021	
21-06-03801-002	121.4-2	06/07/2021	NURSE EXAM ROOM 1F-2	6.98	07/19/2021	
21-06-03801-003	121.4-3	06/07/2021	CAFETERIA CORRIDOR FOUNTAIN 1C-6	19.5	07/19/2021	
21-06-03801-004	121.4-4	06/07/2021	FACULTY BREAK ROOM C-6A 1F-6	10.6	07/19/2021	
21-06-03801-005	121.4-5	06/07/2021	FACULTY DINING ROOM C-20 1F-5	38.6	07/19/2021	
21-06-03801-006	121.4-6	06/07/2021	KITCHEN HAND WASH 1F-8	26.7	07/19/2021	
21-06-03801-007	121.4-7	06/07/2021	KITCHEN CENTER PREP 1F-9	3.40	07/19/2021	
21-06-03801-008	121.4-8	06/07/2021	KITCHEN 3 BAY RIGHT 1F-10	8.65	07/19/2021	
21-06-03801-009	121.4-9	06/07/2021	KITCHEN REAR PREP 1F-11	12.3	07/19/2021	
21-06-03801-010	121.4-10	06/07/2021	KITCHEN REAR 2 BAY 1F-12	29.8	07/19/2021	
21-06-03801-011	121.4-11	06/07/2021	MECHANICAL ROOM HOT WATER TANK 1S-1	28.0	07/19/2021	
21-06-03801-012	121.4-12	06/07/2021	CAFETERIA SERVING FAUCET 1F-7	13.3	07/19/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-06-03801

Project/Test Address: 2020L-121.4; Washington Middle School; 159 Buffalo St; Jamestown, NY 14701

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03801-013	121.4-13	06/07/2021	ROOM C-7 KITCHENETTE 1F-4	3.02	07/19/2021	
21-06-03801-014	121.4-14	06/07/2021	AEROBICS ROOM D-2 LEFT FOUNTAIN 1C-7	<1.00	07/19/2021	
21-06-03801-015	121.4-15	06/07/2021	AEROBICS ROOM D-2 RIGHT FOUNTAIN 1C-8	<1.00	07/19/2021	
21-06-03801-016	121.4-16A	06/07/2021	EAST CORRIDOR FOUNTAIN BY AEROBICS 1C-9	<1.00	07/19/2021	
21-06-03801-017	121.4-16B	06/07/2021	EAST CORRIDOR FOUNTAIN BY AEROBICS 1C-9	<1.00	07/19/2021	
21-06-03801-018	121.4-17	06/07/2021	FITNESS ROOM 1F-13	3.39	07/19/2021	
21-06-03801-019	121.4-18	06/07/2021	EAST CORRIDOR FOUNTAIN BY D-6 1C-10	1.42	07/19/2021	
21-06-03801-020	121.4-19	06/07/2021	FAMILY & CONSUMER SCIENCES D-8 SINK 5 1F-14	5.41	07/19/2021	
21-06-03801-021	121.4-20	06/07/2021	FAMILY & CONSUMER SCIENCES D-8 SINK 4 1F-15	1.97	07/19/2021	
21-06-03801-022	121.4-21	06/07/2021	FAMILY & CONSUMER SCIENCES D-8 SINK 3 1F-16	4.21	07/19/2021	
21-06-03801-023	121.4-22	06/07/2021	FAMILY & CONSUMER SCIENCES D-8 SINK 2 1F-17	5.13	07/19/2021	
21-06-03801-024	121.4-23	06/07/2021	FAMILY & CONSUMER SCIENCES D-8 SINK 1 1F-18	15.1	07/19/2021	
21-06-03801-025	121.4-24	06/07/2021	NORTHWEST CORRIDOR BY BOYS LAV 1C-11	31.1	07/19/2021	
21-06-03801-026	121.4-25	06/07/2021	NORTHWEST CORRIDOR BY GIRLS LAV 1C-12	15.8	07/19/2021	
21-06-03801-027	121.4-26	06/07/2021	FACULTY LOUGHE A-8 1F-19	5.22	07/19/2021	
21-06-03801-028	121.4-27	06/07/2021	NORTHWESTERN CORRIDOR BETWEEN SINGLE LAVS 1C-13	<1.00	07/19/2021	
21-06-03801-029	121.4-28	06/07/2021	CLASSROOM A-13 1F-20	<1.00	07/19/2021	
21-06-03801-030	121.4-29	06/07/2021	WEST CORRIDOR BY B-5 1C-3	8.32	07/19/2021	
21-06-03801-031	121.4-30	06/07/2021	WEST CORRIDOR BY B-8 1C-2	5.72	07/19/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-06-03801

Project/Test Address: 2020L-121.4; Washington Middle School; 159 Buffalo St; Jamestown, NY 14701

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-06-03801-032	121.4-31	06/07/2021	WEST CORRIDOR BETWEEN SINGLE LAVS 1C-1	<1.00	07/19/2021	
21-06-03801-033	121.4-32	06/07/2021	AUDITORIUM LEFT FOUNTAIN 1C-4	<1.00	07/19/2021	
21-06-03801-034	121.4-33	06/07/2021	AUDITORIUM RIGHT FOUNTAIN 1C-5	<1.00	07/19/2021	
21-06-03801-035	121.4-34	06/07/2021	MAIN OFFICE KITCHENETTE 1F-3	4.27	07/19/2021	

Method: EPA 200.8

Analyst: Ailea Cabatbat

Accreditation #: NY 11714

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-121.4

Client: Jamestown CSD

Contact: Carl Pillitteri

Building: Washington Middle School

Location: 159 Buffalo St. Jamestown, NY 14701

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
121.4-1	Nurse Main [1F-1]	S	22:17
121.4-2	Nurse Exam Room [1F-2]	S	22:19
121.4-3	Cafeteria Corridor Fountain [1C-6]	DF	22:21
121.4-4	Faculty Break Room C-6A [1F-6]	S	22:23
121.4-5	Faculty Dining Room C-20 [1F-5]	S	22:25
121.4-6	Kitchen Hand Wash [1F-8]	S	22:27
121.4-7	Kitchen Center Prep [1F-9]	S	22:29
121.4-8	Kitchen 3 Bay Right [1F-10]	S	22:31
121.4-9	Kitchen Rear Prep [1F-11]	S	22:33
121.4-10	Kitchen Rear 2 Bay [1F-12]	S	22:35
121.4-11	Mechanical Room Hot Water Tank [1S-1]	S	22:37
121.4-12	Cafeteria Serving Faucet [1F-7]	S	22:39
121.4-13	Room C-7 Kitchenette [1F-4]	S	22:41
121.4-14	Aerobics Room D-2 Left Fountain [1C-7]	DF	22:43
121.4-15	Aerobics Room D-2 Right Fountain [1C-8]	DF	22:45
121.4-16A	East Corridor Fountain by Aerobics [1C-9]	DF	22:47
121.4-16B	East Corridor Fountain by Aerobics [1C-9]	DFB	22:49
121.4-17	Fitness Room [1F-13]	S	22:51

21-06-03801



Due Date:
07/22/2021
(Thursday)
AE

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

☒ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 6/7/2021

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 6/19/2021

Received (Name / Lab): KTHABBS K. V. Lab Date: 6-23-21 Time: 3:41 pm

Sample Login (Name / Lab): Troy Blum / J. Blum Date: 7/7/21 Time: 3:40 pm

Analysis (Name / Lab): A. C. Alcala / Alcala Date: 7/19/21 Time: 12:14 pm

QA/QC Review (Name / Lab): M. W. Smith Date: 7/19/21 Time: 2 pm

Archived / Released: QA/QC InterLAB Use: Date: Time:



Chain of Custody Document

Submitted to: (Lab Name) EHS

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

STOHL Job # 2020L-121.4

Client: Jamestown CSD

Contact: Carl Pillitteri

Building: Washington Middle School

Location: 159 Buffalo St. Jamestown, NY 14701

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
121.4-18	East Corridor Fountain by D-6 [1C-10]	DF	22:53
121.4-19	Family & Consumer Science D-8 Sink 5 [1F-14]	S	22:55
121.4-20	Family & Consumer Science D-8 Sink 4 [1F-15]	S	22:57
121.4-21	Family & Consumer Science D-8 Sink 3 [1F-16]	S	22:59
121.4-22	Family & Consumer Science D-8 Sink 2 [1F-17]	S	23:01
121.4-23	Family & Consumer Science D-8 Sink 1 [1F-18]	S	23:03
121.4-24	Northwest Corridor by Boys Lav [1C-11]	DF	23:05
121.4-25	Northwest Corridor by Girls Lav [1C-12]	DF	23:07
121.4-26	Faculty Lounge A-8 [1F-19]	S	23:09
121.4-27	Northwestern Corridor Between Single Lavs [1C-13]	DF	23:11
121.4-28	Classroom A-13 [1F-20]	S	23:13
121.4-29	West Corridor by B-5 [1C-3]	DF	23:15
121.4-30	West Corridor by B-8 [1C-2]	DF	23:17
121.4-31	West Corridor Between Single Lavs [1C-1]	DF	23:19
121.4-32	Auditorium Left Fountain [1C-4]	DF	23:21
121.4-33	Auditorium Right Fountain [1C-5]	DF	23:23
121.4-34	Main Office Kitchenette [1F-3]	S	23:25

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Christine Schultz Print Name Christine Schultz Date: 6/7/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Date: 6/19/2021

Received (Name / Lab): K. Haines Date: 6.23.21 Time: 3:41 pm

Sample Login (Name / Lab): Tina Bloom / Haines Date: 7/7/21 Time: 3:45 PM

Analysis (Name / Lab): Alexa Cabatbat Date: 7/19/21 Time: 1:11 pm

QA/QC Review (Name / Lab): Memo Date: 7/19/21 Time: 2pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____